Graymont Western US Inc. Suite 301, 3950 South 700 East	HSBC BANK USA NA · Buffalo, NY 14203		
PAY ONE THOUSAND ONE HUNDRED FIFTY AND 00/100******** TO THE ORDER OF Division of Oil, Gas and Mining PO Box 145801 Suite 301, 3950 South 700 East Suite 301, 3950 South 700 East South 700 East Suite 301, 3950 South	DATE [mm/dd/yyyy] 01/16/2013	AMOUNT \$*****1,150.00	00104
G AND 00/100	**************************************		
TO THE ORDER OF Division of Oil, Gas and Mining PO Box 145801 Salt Lake City UT 84114-5801	ORESTOR FRANCIAL SERVICES		
	SRichardo CORPORATE CONTROLLER		

R647 rules under the Utah Minerals Regulatory Program. It is due January 31 of each year.

1.	Mine Permit Number: 127006		
2.	Mine Name: Cricket Mountain Quarry		
3.	Name of Operator/Permittee: 6 Fagment Weste	TO 05	
	Note: If Operator's address, company representative or phone number have changed for the Notice of Intention together with form MR-REV available on the Division's https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-REV.pdf .	, please provide a replacement page web page at RECEIVED	
4.	Report the gross amount of ore mined and waste moved:	JAN 2 3 2013	
	Gross Ore Mined 1,106,270 Tons, oryd ³ Waste Material Moved 299, 905 Tons, oryd ³	DIV. OF OIL, GAS & MINING	
5.	New disturbance created during the year Area reclaimed during the year Total disturbed area at the end of the year *The total disturbed area should not be greater than the permitted.	Acres 7, 2 Acres 14, 8 Acres* 2d/bonded acreage	
6.	Briefly describe the reclamation work performed during the past y	vear. (Submit form MR-	